PAGE 1 of 1 212.1-0809

SERVICE



PAPER MACHINERY CORPORATION

8900 West Bradley Road Milwaukee, WI 53224 (PHONE) 414-354-8050 (FAX) 414-354-8614 www.papermc.com

INTERNAL WEAR 090123 No. 212.1

> **TURRET FOLLOWERS** PMC-1001 & PMC-1002

Field reports have indicated a potential problem of the Turret Assembly, in the Lower Drive Compartment: Internal wear of the Turret Followers.

Because external inspection may appear good, internal wear can go undetected. PMC offers the attached procedure (Instruction 095.1) on how to check for internal wear.

CONTACTS:

Parts orders and customer communication can be made using telephone, FAX, or e-mail. Contact can still be made using the main telephone switchboard at 414-354-8050 or FAX number 414-354-8614. Sending a FAX directly to the Service Department, at 414-354-1710, will convey a faster response. If using e-mail and no response is made within 3 working days, please contact via phone or FAX.

Parts orders & inquiries can be directed to Holly Warner or Vicky Alcaraz using telephone, FAX, or e-mail. Please make sure to carbon copy (CC) both Holly Warner and Vicky Alcaraz in all e-mails containing parts orders. Service issues & support can be directed to Mike Ferguson or Bill Paplham; please carbon copy (CC) both Mike Ferguson and Bill Paplham in all e-mails. Electrical issues and support directed to Larry Spencer. Contact Bill Paplham for scheduled service trips and Mike Ferguson for training.